2. Site Closed:

New Year's Day Memorial Day Thanksgiving Day All Sundays July 4th Labor Day Christmas Day

D. SCHEDULING:

Customers please call truck dispatch toll free in California at (800) 742-1671 or out of state call (209) 386-0581 to schedule all shipments before the shipment is made.

ALL APPROVED WASTE STREAMS FOR WHICH K.H. HAS RECEIVED AT LEAST PRIOR DAY NOTIFICATION AND ARRIVE AT THE TIME AGREED WILL BE HANDLED BEFORE THOSE THAT DO NOT. DELAYS FOR NON-SCHEDULED LOADS CAN BE IN EXCESS OF A DAY.

E. LAB PACKS:

- Lab Packs may only contain materials of a single hazard class and may not have any container greater than a one gallon if the container is glass; 5 gallons if other material.
- Solids contaminated with cyanides or sulfides may be accepted in Lab Packs.
- Waste materials effected by the Federal Land Disposal Ban are required to be lab-packed separately or repackaged and may require incineration. Some banned wastes may not be acceptable in lab-packs.

F. <u>CALL OUT REQUIREMENTS:</u>

Weekends and holidays, overtime or call out requires a minimum of 24-hours notice to be given no later than 3:00 p.m. Friday or the last normal working day.

G. DEFINITIONS AND PERMITS:

- Extremely Hazardous (E.H.) wastes are defined by the California Department of Health Services. An extremely hazardous waste requires a permit be granted by the Department of Health Services. The permit number, and a copy of the permit application must be on file at the K.H. Facility before the waste can be received. This E.H. permit can be made valid for up to one year at a time.
- Wastes subject to Federal Land Disposal restrictions require appropriate notification and/or certification forms to accompany each manifested shipment as indicated in 40 CFR, Part 268.
- RCRA "Empty" is defined as the drum containing no more than one inch of residue. In addition, the residue may not exceed 3 percent of the weight of the original contents. Ref: 40 CRF Paragraph 261.7. Other restrictions may apply. Containers formerly holding acutely hazardous waste must be triple rinsed before they can be defined as empty. Ref: 40 CFR Paragraph 261.33.